


Summary of Physical Inspection Reports of 3013 Infrastructure sites under USOF's Mobile Infrastructure Phase-I Scheme


- CCA offices have conducted physical inspection of 5561 infrastructure sites, which is 76% of 7284 infrastructure sites declared RFI as on 31st December, 2011.
- As a measure to improve the monitoring of the scheme, the system to receive the physical inspection reports from Circle CCA office was computerized in September 2010. Since then, USOF HQ has received the physical inspection reports (in new computerized format) for 3013 infrastructure sites. Hence, this report covers physical inspection reports of only these 3013 infrastructure sites.

General Layout




Total No.	Number of Compliant Cases						
3013	2975	2980	2952	3013	2957	2998	2965

Security




Total No.	Number of Compliant Cases	
3013	2998	2869

Charging Facility




Total No.	Number of Compliant Cases	
3013	2663	2479

Sign Board




Total No.	Number of Compliant Cases			
3013	2793	1548	2656	2767

Power Facilities.....(Page 1/2)




Total No.	Number of Compliant Cases				
3013	2333	2989	2640	485	2856

Power Facilities.....(Page2/2)




Total No.	Number of Compliant Cases					
3013	1284	1817	2035	2191	2975	2986

Structure and Design




Total No.	Number of Compliant Cases						
3013	2968	2933	2986	2946	2743	1168	2370

Mobile Services(Page1/2)



Total No.	Number of Compliant Cases		
3013	1210	1845	2258

Mobile Services(Page2/2)



Total No.	Number of Compliant Cases			
3013	940	1012	742	319